

VKM 16101

Technical Bulletin R1

Issued: 2008-01-01




Renault / Volvo / Opel-Vauxhall (Renault engines)



Design differences (pulley diameter)



For this manual tensioner, in the past, 2 designs were available: one with a 50 mm pulley and an old one with a 52 mm pulley. Today, some applications might still be equipped of the old 52 mm pulley but there is no problem to service them with the 50 mm design.



Install Confidence

www.vsm.skf.com



VKM 16101

Technical Bulletin R1

Issued: 2008-01-01

There are no changes concerning either applications or OE numbers.

Install Confidence

www.vsm.skf.com

